

Q21-34

plâtre calorifuge

Building

Q21 MORLANWELZ
RUE R. WAROQUE 3
7140 MORLANWELZ
Province Hainaut

Status

TO BE ABANDONED (decided to leave portfolio)

Type

Commercial

Profit Center

REPM - AGENCES STATUTAIRES(REPM - AGENCE)

Owner code

3000000000

Administrative data

Inventarist

AV ECOSAFER

Id

AIB5

Inventory on

Friday, 21 June 2002

Construction year

1900-01-01

Inventory data

Floor / room / place
-1 / chaufferie /

Label in place

Yes

Quantity

SampleTakenBy

AsbestosClass

Unbound

AsbestosColor

wit - blanc

AsbestosType

Amosite

PersonsPresenc

PersonsNature

Sample

Taken o

Remarks



Recommended Measure

enlevement urgent

Instructions

ne pas toucher sac couveuse, gants, masque, tyvek

History of Inspection(s) / Action(s)

Date	Type	Score	Info
02/08/2002	Work	REM	- Verwijderd -

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Serious Damage			Freely Accessible		No		1-50%	U1
current	Serious Damage			Freely Accessible		No		1-50%	REM

Building

Q21 MORLANWELZ
RUE R. WAROQUE 3
7140 MORLANWELZ
Province Hainaut

Status

TO BE ABANDONED (decided to leave portfolio)

Type

Commercial

Profit Center

REPM - AGENCES STATUTAIRES(REPM - AGENCE)

Owner code

3000000000

Administrative data

Inventarist

AV ECOSAFER

Id

AIB5

Inventory on

Friday, 21 June 2002

Construction year

1900-01-01

Q21-35

plâtre calorifuge

Inventory data

Floor / room / place

-1 / chaufferie /

Label in place

No

Quantity

SampleTakenBy

AsbestosClass

Unbound

AsbestosColor

wit - blanc

AsbestosType

Amosite

PersonsPresenc

PersonsNature

Sample

Taken o

Remarks

Recommended Measure

enlevement urgent

Instructions

ne pas toucher sac couveuse, gants,masque,tyvek

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Serious Damage			Freely Accessible		No		1-50%	U1
current	Serious Damage			Freely Accessible		No		1-50%	REM

Building

Q21

MORLANWELZ

RUE R. WAROQUE 3

7140 MORLANWELZ

Province Hainaut

Status

TO BE ABANDONED (decided to leave portfolio)

Type

Commercial

Profit Center

REPM - AGENCES STATUTAIRES(REPM - AGENCE

Owner code

3000000000

Administrative data

Inventarist

AV ECOSAFER

Id

AIB5

Inventory on

Friday, 21 June 2002

Construction year

1900-01-01

Q21-36

plâtre calorifuge

Inventory data

Floor / room / place

-1 / chaufferie /

Label in place No

Quantity

SampleTakenBy

AsbestosClass Unbound

AsbestosColor wit - blanc

AsbestosType Amosite

PersonsPresenc

PersonsNature

Sample Taken o

Remarks



Recommended Measure

enlevement urgent

Instructions

ne pas toucher sac couveuse, gants, masque,
tyvek

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Serious Damage			Freely Accessible		No		1-50%	U1
current	Serious Damage			Freely Accessible		No		1-50%	REM

Building

Q21 MORLANWELZ
RUE R. WAROQUE 3
7140 MORLANWELZ

Province Hainaut

Status TO BE ABANDONED (decided to leave portfolio)
Type Commercial
Profit Center REPM - AGENCES STATUTAIRES(REPM - AGENCE
Owner code 3000000000

Administrative data

Inventarist AV ECOSAFER
Id AIB5
Inventory on Friday, 21 June 2002
Construction year 1900-01-01

History of Inspection(s) / Action(s)

Date	Type	Score	Info
02/08/2002	Work	REM	- Verwiiderd l -

Q21-37

plâtre calorifuge

Inventory data

Floor / room / place

-1 / chaufferie /

Label in place

No

Quantity

SampleTakenBy

AsbestosClass

Unbound

AsbestosColor

wit - blanc

AsbestosType

Amosite

PersonsPresenc

PersonsNature

Sample

Taken o

Remarks

Recommended Measure

enlevement urgent

Instructions

ne pas toucher sac couveuse, gants,masque, tyvek

History of Inspection(s) / Action(s)

Date	Type	Score	Info
02/08/2002	Work	REM	- Verwiiderd l -

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Serious Damage			Freely Accessible		No		1-50%	U1
current	Serious Damage			Freely Accessible		No		1-50%	REM

Building

Q21

MORLANWELZ

RUE R. WAROQUE 3

7140 MORLANWELZ

Province Hainaut

Status

TO BE ABANDONED (decided to leave portfolio)

Type

Commercial

Profit Center

REPM - AGENCES STATUTAIRES(REPM - AGENCE

Owner code

3000000000

Administrative data

Inventarist

AV ECOSAFER

Id

AIB5

Inventory on

Friday, 21 June 2002

Construction year

1900-01-01

Inventory data

Floor / room / place
-1 / couloir /

Label in place No
Quantity
SampleTakenBy
AsbestosClass Unbound
AsbestosColor wit - blanc
AsbestosType Amosite
PersonsPresenc
PersonsNature
Sample Taken o
Remarks



Recommended Measure
enlevement court terme

Instructions
ne pas toucher sac couveuse, gants, masque,
tyvek

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Superficial Damage			Freely Accessible		No		1-50%	U2
current	Superficial Damage			Freely Accessible		No		1-50%	REM

Building

Q21 MORLANWELZ
RUE R. WAROQUE 3
7140 MORLANWELZ
Province Hainaut

Status TO BE ABANDONED (decided to leave portfolio)
Type Commercial
Profit Center REPM - AGENCES STATUTAIRES(REPM - AGENCE
Owner code 3000000000

Administrative data

Inventarist AV ECOSAFER
Id AIB5
nventoried on Friday, 21 June 2002
Construction year 1900-01-01

Q21-39

plâtre calorifuge

Inventory data

Floor / room / place

-1 / Sas chaufferie /

Label in place No

Quantity

SampleTakenBy

AsbestosClass Unbound

AsbestosColor wit - blanc

AsbestosType Amosite

PersonsPresenc

PersonsNature

Sample Taken o

Remarks



Recommended Measure

enlevement urgent - assainissement

Instructions

ne pas toucher sac couveuse, gants, masque,
tyvek

History of Inspection(s) / Action(s)

Date	Type	Score	Info
02/08/2002	Work	REM	- Verwiiderd l -

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Serious Damage			Freely Accessible		No		1-50%	U1
current	Serious Damage			Freely Accessible		No		1-50%	REM

Building

Q21 MORLANWELZ
RUE R. WAROQUE 3
7140 MORLANWELZ

Province Hainaut

Status TO BE ABANDONED (decided to leave portfolio)
Type Commercial
Profit Center REPM - AGENCES STATUTAIRES(REPM - AGENCE
Owner code 3000000000

Administrative data

Inventarist AV ECOSAFER
Id AIB5
Inventory on Friday, 21 June 2002
Construction year 1900-01-01

Inventory data

Floor / room / place
-1 / sas chaufferie /

Label in place No
Quantity
SampleTakenBy
AsbestosClass Unbound
AsbestosColor wit - blanc
AsbestosType Amosite
PersonsPresenc
PersonsNature
Sample Taken o
Remarks



Recommended Measure
assainissement urgent

Instructions
ne pa stoucher sac couveuse, gants,masque,
tyvek

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Serious Damage			Freely Accessible		No		1-50%	U1
current	Serious Damage			Freely Accessible		No		1-50%	REM

Building

Q21 MORLANWELZ
RUE R. WAROQUE 3
7140 MORLANWELZ
Province Hainaut

Status TO BE ABANDONED (decided to leave portfolio)
Type Commercial
Profit Center REPM - AGENCES STATUTAIRES(REPM - AGENCE
Owner code 3000000000

Administrative data

Inventarist AV ECOSAFER
Id AIB5
nventoried on Friday, 21 June 2002
Construction year 1900-01-01

Q21-41

plâtre calorifuge

Inventory data

Floor / room / place

-1 / pied escalier /

Label in place

No

Quantity

SampleTakenBy

AsbestosClass

Unbound

AsbestosColor

wit - blanc

AsbestosType

Amosite

PersonsPresenc

PersonsNature

Sample

Taken o

Remarks

Recommended Measure

enlevement court terme

Instructions

ne pas toucher sac couveuse, gants,masque, tyvek

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Superficial Damage			Freely Accessible		No		1-50%	U2
current	Superficial Damage			Freely Accessible		No		1-50%	REM

Building

Q21

MORLANWELZ

RUE R. WAROQUE 3

7140 MORLANWELZ

Province Hainaut

Status

TO BE ABANDONED (decided to leave portfolio)

Type

Commercial

Profit Center

REPM - AGENCES STATUTAIRES(REPM - AGENCE

Owner code

3000000000

Administrative data

Inventarist

AV ECOSAFER

Id

AIB5

Inventory on

Friday, 21 June 2002

Construction year

1900-01-01

Q21-42

plâtre calorifuge

Inventory data

Floor / room / place

-1 / serveur /

Label in place No

Quantity

SampleTakenBy

AsbestosClass Unbound

AsbestosColor wit - blanc

AsbestosType Amosite

PersonsPresenc

PersonsNature

Sample Taken o

Remarks



Recommended Measure

enlevement long terme

Instructions

ne pas toucher sac couveuse, gants, masque,
tyvek

History of Inspection(s) / Action(s)

Date	Type	Score	Info
02/08/2002	Work	REM	- Verwiiderd l -

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Intact			Freely Accessible		No		1-50%	U2
current	Intact			Freely Accessible		No		1-50%	REM

Building

Q21 MORLANWELZ
RUE R. WAROQUE 3
7140 MORLANWELZ

Province Hainaut

Status TO BE ABANDONED (decided to leave portfolio)
Type Commercial
Profit Center REPM - AGENCES STATUTAIRES(REPM - AGENCE
Owner code 3000000000

Administrative data

Inventarist AV ECOSAFER
Id AIB5
Inventory on Friday, 21 June 2002
Construction year 1900-01-01

Inventory data

Floor / room / place
toiture / extérieur /

Label in place No
Quantity
SampleTakenBy
AsbestosClass Bound
AsbestosColor coloré - gekleurd
AsbestosType Chrysotile
PersonsPresenc
PersonsNature
Sample Taken o
Remarks



Recommended Measure
observation

Instructions
ne pas abimer eviter la poussiere

History of Inspection(s) / Action(s)			
Date	Type	Score	Info
08/02/2002	Work	REM	- Verwiiderd -
04/01/2004	Inspection	REM	- -

EPA Score:

	A_MaterialCondition	B_WaterDamage	C_ExposedSurface	D_Accessibility	E_Mobility	F_Ventilation	G_Brittleness	H_AsbestosLevel	Score
initial	Intact			Not Accessible		No		1-50%	U9
current	Intact			Not Accessible		No		1-50%	REM